Report #477477

1983 Porsche 930





Summary

I have inspected this 1983 Porsche 930 and made note of any issues I found below.

This vehicle looks to have been well kept with minor issues of note. I found no obvious signs of the vehicle having prior major accident or flood damage. The exterior shows very little wear with what is considered to be appropriate for the age of the vehicle. There are minor scratches present around the exterior of the vehicle that are considered normal with age, most are too small to see in photos. I checked the vehicle with a magnet and found it to stick all around but was weaker in the lower panels, but not excessively so. The exterior lighting functions as designed. All four wheels show light wear consistent with the age of the vehicle.

The interior shows well with only light wear noted. The steering wheel shows a light amount of wear consistent with the age of the vehicle. The seats show a light amount of wear present that is considered normal for the age of the vehicle. The air conditioning does not work. The compressor belt has been removed from the vehicle. The carpet shows a light amount of wear that is appropriate for the age of the vehicle. The headliner shows a light amount of wear that is considered normal for the age of the vehicle. I found that the entertainment system functions as designed along with the interior lighting.

Moving my inspection to focus on the mechanical components of the vehicle, I did not observe any signs of leaks or seepages present from the underside of the vehicle. Looking under the hood I observed that the vehicle's serviceable fluids are at their proper level and are a healthy color. All four tires are an appropriate size for the vehicle and show an even wear pattern. All four tires have a sufficient amount of tread depth left.

I found no issues on the test drive. The engine had plenty of power and there were no misfires. The transmission shifted as designed with no harsh engagement or slipping. The steering was responsive and the suspension was firm and the vehicle handled well. There were no abnormal vibrations or odd noises. The brakes were firm with no pulsation felt.

See below and pictures for more info.

Vehicle Informat	ion
Year	1983
Make	Porsche
Model	930
VIN	Wp0zzz9szd6000961
Stock No.	N/A
Mileage	66793
Engine Cylinders	6 Cylinder
Exterior Color	Maroon
Interior Color	Grey
Interior Material	Leather
Engine Number	N/A
Transmission Number	N/A
Fuel Type	Gas

Drivetrain	
Transmission	Manual
Drive Type	Rear Wheel
	Drive

Road Test	
Road Test	ı
Road Test	Good
Engine Starting Easily	Good
Engine running well after Started	Good
Transmission performance	Good
Clutch Performance	Good
Differential Performance	Good
Wheel Bearing Performance	Good
Braking Performance	Good
Suspension Performance	Good
Steering Performance and Alignment	Good

Niper Blades	Good
 Body Panel Alignment	Good
Scratches	Issues
There are minor scratches pre	esent around the
exterior of the vehicle that are with age, most are too small to	
Paint Condition	Good
 Seals	Good
Rust	Good
Exterior Lights	Good
Power Sunroof	Good
Power Door Mirrors	Good
Bumpers	Good
Underbody/Frame	Good
Condition	Cood
Glass	Good
Floors	Good
Rockers	Good
Quarter Panels	Good
Body Filler Used	Issues
I checked the vehicle with a m	agnet and found it to
stick all around but was weake	er in the lower panels,
but not excessively so.	
Hood	Good
Doors	Good
Dings	Good
Dents	Good
Chrome	Good

Interior	
Steering Wheel	Issues
The steering wheel shows a light	
consistent with the age of the ve	hicle.
Horn	Good
Seat Condition	Issues
The seats show a light amount of is considered normal for the age	
Seat Belts	Good
Clock	Good
Radio/Navigation/DVD	Good
Inner Door Panels	Good
Power Locks	Good
Power Window Switches	Good
Dash	Good
Dash Lights Working	Good
Air Conditioning	Issues
The air conditioning does not wo belt has been removed from the	•
Heater	Good
Rear Defroster	Good
Carpet	Issues
The carpet shows a light amount	of wear that is
appropriate for the age of the ve	hicle.
Signs of Smoking?	Good
Cup Holders	Good
Headliner	Issues
The headliner shows a light amo considered normal for the age of	
Blower Motor	Good
Instrument Cluster/Gauges	Good
Unusual Odors	Good
Window Function	Good
Interior Trim	Good
Sun Visors	Good


Mechanical	
Air Filter	Good
Battery Condition	Good
Charging System	Good
Cooling Fan Condition Mechanical/Electronic	Good
Hoses and Clamps Age/Cracking	Good
Belts	Good
Power Steering System	Good
Power Steering Fluid Condition	Good
Engine Oil Condition	Good
Engine Oil Leaks	Good
Transmission Fluid Condition	Good
Transmission Fluid Leaks	Good
Brake System Condition	Good
Brake Fluid Leaks	Good
Transfer Case Leaks	Good
Differential leaks	Good
Muffler System	Good
CV Boots and Joints	Good
Shocks and bushings Condition. Leaking?	Good
Ball Joints and Tie Rods	Good
Ball Joints and Tie Rods	Good

Manufacturer	
river's Front Tire	Yokohama
assenger's Front Tire	Yokohama
Priver's 1st Axle Outer	Yokohama
assenger's 1st Axle Outer Tire	Yokohama
Size	
Driver's Front Tire	235/40R17
assenger's Front Tire	235/40R17
Oriver's 1st Axle Outer Fire	235/40R17
Passenger's 1st Axle Duter Tire	235/40R17
Tire Condition	
Oriver's Front Tire	No Issues
Passenger's Front Tire	No Issues
Oriver's 1st Axle Outer Fire	No Issues
Passenger's 1st Axle Duter Tire	No Issues
Wheel Condition	
Oriver's Front Tire	No Issues
Oriver's 1st Axle Outer Fire	No Issues
Passenger's Front Tire	No Issues
Passenger's 1st Axle Duter Tire	No Issues
Tire Tread	
Oriver's Front Tire	10/32
Passenger's Front Tire	10/32
Oriver's 1st Axle Outer	10/32
Passenger's 1st Axle Duter Tire	10/32
Spare Tire	No

Vehicle Images

















Front trunk






Vehicle info


































Mileage before road test





After market radio



















































































Dash area








































Engine compartment info






























Ac compressor

























































































Mileage after road test







