

Report #489304

1967 Chevrolet Chevelle



Summary

This classic looks to have been well kept with minor issues of note and several professional upgrades. I found no obvious signs of the vehicle having prior major accident or flood damage. There are minor misc. scratches around the vehicle. Normal for mileage and most too small to see in photos. The underside shows areas of very minor surface rust. See pictures. The body seals around the windows are showing signs of age and wear. This includes the doors, windows, trunk, and other miscellaneous body seals. They will need replacement. The exterior shows very little wear with what is considered to be appropriate for the age and mileage of the restoration.

The interior shows well with only light wear noted. There is light wear to the seats. Normal for mileage. The radio does not work. The inner door panels show wear consistent with age and mileage. The interior trim shows normal wear consistent with age and mileage. The carpet shows normal wear consistent with age and mileage. All other accessories are working as designed.

I found no issues on the test drive. The engine had plenty of power and there were no misfires. The transmission shifted as designed with no harsh engagement or slipping. The steering was responsive and the suspension was firm and the vehicle handled well. There were no abnormal vibrations or odd noises. The brakes were firm with no pulsation felt. There were no leaks found to the underside of the vehicle. This vehicle has been modified from the chassis to the engine with suspension parts, power disc brakes, Racing style shocks, and interior features like digital gauges. All look to have been done professionally. See below and pictures for more info.










Vehicle Information

| | |
|---------------------|---------------|
| Year | 1967 |
| Make | Chevrolet |
| Model | Chevelle |
| VIN | 136177B188374 |
| Stock No. | N/A |
| Mileage | 2631 |
| Engine Cylinders | 8 Cylinder |
| Exterior Color | Red |
| Interior Color | Red |
| Interior Material | Leather |
| Engine Number | N/A |
| Transmission Number | N/A |
| Fuel Type | Gas |





















Drivetrain

| | |
|--------------|------------------|
| Transmission | Automatic |
| Drive Type | Rear Wheel Drive |



















Road Test

| | |
|------------------------------------|--|
| Road Test |  Good |
| Engine Starting Easily |  Good |
| Engine running well after Started |  Good |
| Transmission performance |  Good |
| Differential Performance |  Good |
| Wheel Bearing Performance |  Good |
| Braking Performance |  Good |
| Suspension Performance |  Good |
| Steering Performance and Alignment |  Good |
























Exterior

| | |
|---|--|
| Wiper Blades |  Good |
| Windshield Washer |  Good |
| Body Panel Alignment |  Good |
| Scratches |  Issues |
| There are minor misc scratches around the vehicle. Normal for mileage and most too small to see in photos. | |
| Paint Condition |  Good |
| Seals |  Issues |
| The body seals around the windows are showing signs of age and wear. This includes the doors, windows, trunk, and other miscellaneous body seals. They will need replacement. | |
| Rust |  Issues |
| The underside shows areas of very minor surface rust. See pictures. | |
| Exterior Lights |  Good |
| Power Door Mirrors |  Good |
| Bumpers |  Good |
| Underbody/Frame Condition |  Good |
| Glass |  Good |
| Floors |  Good |
| Rockers |  Good |
| Quarter Panels |  Good |
| Hood |  Good |
| Doors |  Good |
| Dings |  Good |
| Dents |  Good |
| Chrome |  Good |

Interior

| | |
|--|--|
| Steering Wheel |  Good |
| Horn |  Good |
| Seat Condition |  Issues |
| There is light wear to the seats. Normal for mileage. | |
| Radio/Navigation/DVD |  Issues |
| The radio does not work. | |
| Inner Door Panels |  Issues |
| The inner door panels show wear consistent with age and mileage. | |
| Dash |  Good |
| Dash Lights Working |  Good |
| Air Conditioning |  Good |
| Heater |  Good |
| Carpet |  Issues |
| The carpet shows normal wear consistent with age and mileage. | |
| Floor Mats |  Good |
| Headliner |  Good |
| Blower Motor |  Good |
| Instrument Cluster/Gauges |  Good |
| Unusual Odors |  Good |
| Window Function |  Good |
| Interior Trim |  Issues |
| The interior trim shows normal wear consistent with age and mileage. | |
| Sun Visors |  Good |

Mechanical

| | |
|--|--|
| Air Filter |  Good |
| Battery Condition |  Good |
| Charging System |  Good |
| Cooling Fan Condition Mechanical/Electronic |  Good |
| Hoses and Clamps Age/Cracking |  Good |
| Radiator Condition |  Good |
| Engine Coolant Condition |  Good |
| Belts |  Good |
| Power Steering System |  Good |
| Power Steering Fluid Condition |  Good |
| Engine Oil Condition |  Good |
| Engine Oil Leaks |  Good |
| Transmission Fluid Condition |  Good |
| Transmission Fluid Leaks |  Good |
| Brake System Condition |  Good |
| Brake Fluid Leaks |  Good |
| Differential leaks |  Good |
| Muffler System |  Good |
| CV Boots and Joints |  Good |
| Shocks and bushings Condition. Leaking? |  Good |
| Ball Joints and Tie Rods |  Good |
| Radiator Cap Sealing Properly |  Good |
| Coolant Leaks |  Good |

Tire / Wheels

| Manufacturer | |
|------------------------------------|-----------|
| Driver's Front Tire | Falken |
| Passenger's Front Tire | Faulken |
| Driver's 1st Axle Outer Tire | Faulken |
| Passenger's 1st Axle Outer Tire | Faulken |
| Size | |
| Driver's Front Tire | 255/45r18 |
| Passenger's Front Tire | 255/45r18 |
| Driver's 1st Axle Outer Tire | 255/45r18 |
| Passenger's 1st Axle Outer Tire | 255/45r18 |
| Tire Condition | |
| Driver's Front Tire | No Issues |
| Passenger's Front Tire | No Issues |
| Driver's 1st Axle Outer Tire | No Issues |
| Passenger's 1st Axle Outer Tire | No Issues |
| Wheel Condition | |
| Driver's Front Tire | No Issues |
| Driver's 1st Axle Outer Tire | No Issues |
| Passenger's Front Tire | No Issues |
| Passenger's 1st Axle Outer Tire | No Issues |
| Tire Tread | |
| Driver's Front Tire | 8/32 |
| Passenger's Front Tire | 8/32 |
| Driver's 1st Axle Outer Tire | 10/32 |
| Passenger's 1st Axle Outer Tire | 10/32 |
| Spare Tire | No |

Vehicle Images




























































































































DO NOT MOUNT
ON 13.5 INCH RIM.

255 / 45ZR18 100

ALL-STAR



















ELITE

AUTO SHIELD

PLEASE DO NOT WASH
or clay, polish wax or apply
sealants on this vehicle as it
could cause damage to the
protective systems installed.

INSTALL DATE

6/30/2020

SERIAL NUMBER

101033314770

INSTALLED BY

Elite Auto Shield

BRAND

Waxedshine SHC







ODOMETER MILES
002627.7
9:57













