REPORT #434127



1931 Ford Model A Custom Roadster Coupe



I started this inspection off with a look at the title paperwork. A current AZ title was present with box C (Not actual) mileage. He also presented a copy of the Pennsylvania title of where the title was issued before switching to AZ. Just wanted to note that this was a very nice, but a full custom roadster. There was very little, if anything left stock. I walked around the exterior of the vehicle. The custom green paint was very nice. I noted few imperfections in the paint front to back. These were located on the left upper door section, left front fender area top section, right front fender top section, lower trunk lid area and lower left front door area. This vehicle has no convertible top available as it wasn't designed into it during its custom build. The exterior lighting appears to be all LED and operates. There was also green LED strips running from the inside interior, trunk area. underneath the vehicle, wheels wells and engine compartment. I didn't see any reverse lights or license plate lighting operating at time of inspection. With the hood, trunk lid and both reverse opening doors closed. I noticed uneven panel gaps in places on all above mentioned components. The owner stated that this vehicle's green paint has 16 coats currently on it. I measured .90mm with my paint meter which is very thick. I normally see .10-.20mm on average for comparison. The custom wheels are an off set, staggered type with 195/55R15 in front and 245/50R16 in rear. The tire brands don't match from front to rear, but all have plenty of tread present but unknown age of the tires. Inside the trunk area contains a fuel cell under the carpet along with all the wiring for the

audio and air pump for the rear suspension. No spare tire or hardware. The trunk lid has a pop release with a little leather loop, he stated that it sticks once in a while when trying to open. Under the vehicle appears very clean with many custom touches. With the type of wheels currently on, I wasn't able to see or inspect the brakes. The license plate pops down automatically when the vehicle is started.

Next, I moved into the interior. Both the left and right side doors open reversely and from the inside handles only. No exterior handles are present. The doors don't open fully, so getting in and out can be a little tricky. The owner stated that the leather seats and inner door panels are all custom from the same location. The seat belts operated but are not a full standard type seat belt, more of just a chest piece. The instrument cluster was all digital. I had a hard time trying to capture the odometer in the pictures. When looking at the odometer through the camera, the cluster LEDs cycled too quickly, but was normal when looking with out the camera. (See videos for odometer readings) This was the only way to capture it. The vehicle has no AC, heater, power steering, or power anything. The vehicle has one manual operated wiper arm/blade, no washers. The horn operated along with the manual controled switches for the cooling fan, audio, bluetooth, etc. The vehicle has custom steering wheel, floor pedals and the ignition switch hidden under the right side if the dash assembly. Some paint chipping can be seen on the underside of the dash in places (See pictures)

Next, I moved onto the engine area. I was informed by the owner that the engine is a small block Chevy 350cu.in. The engine is built up with chrome components, headers, large 4bbl carburetor and intake. He wasn't sure what type of automatic transmission it was and I wasn't able to tell with the low ground clearance and limited access. The engine oil and transmission fluid levels were full and clean. I did notice a few drips on the ground under the crank dampener area that appeared to be coolant. I also noticed what looked like coolant pooling up in the intake are. I also noticed oil saturation on the sides of the reward section of the engine around the cylinder head areas and lower around the area of the bell housing and backside of the engine. I also noticed what looked like drill marks on the right side bell housing area, right before the starter. The vehicle started right up, seemed to stumble a little when cold and as it warmed up, this seemed to improve. The vehicle has a nice mellow rumble to it at idle. The owner activated the exhaust cut outs and this opened up the exhaust for a very loud rumble. The owner stated the the brake booster is an electronic type as a normal vacuum booster wouldn't work due to clearance issues.

Lastly, I went on a road test. The vehicles turning radius appears to be large, multiple attempts of forwarding and reversing may be needed in tight spots and with no power steering, it may get difficult. The vehicle had good acceleration and braking. I noticed some suspension type noises when turning and /or when going over bumps. No pulling present in the wheel, but it may follow road crown. The cooling fan comes on automatically and also manually with a toggle switch. Once back to the house and shut down for a few minutes. We re-started the vehicle at which point turned over very slow but did start and run.

Please see below for pictures and more info.

Vehicle Info	
Year - 1931	
Make - Ford	
Model - Model A Custom Roadster Coupe	

Mechanical	
Air Filter	>
Battery Condition	/
Charging System	~

Mileage - 1433
Transmission - Automatic
VIN Number - SW133750PA
Interior - Leather
Interior Color - Black
Body Color - Green
Engine - 8 Cylinder
Drive Type - Rear Wheel Drive
Fuel Type - Gas

Exterior	
Wiper Blades	X
Only 1 manually operated wiper arm	
Body Alignment	X
General misalignment to body panels, see pictures.	
Scratches	X
There are minor misc scratches around the vehicle. No and most too small to see in photos.	rmal for mileage
Dings	· ·
Dents	V
Paint Condition	X
The paint shows some small chips and wear in places.	
Exterior Lights	X
I didn't see the license plate light operating and didn't slighting.	ee any reverse
Door Mirrors	V
Bumpers	V
Convertible Top	X
There is no top available	•
Glass	~
Hood	X
Panel gaps present	•
Doors	X
Panel gaps present	
Floors	V
Rockers	V
Quarter Panels	V
Chrome	- 1

Interior	
Steering Wheel	✓
Horn	/
Seat Condition	/
Seat Belts	X
It's just a one piece chest belt, no lap section.	
Radio/Navigation	/
Inner Door Panels	~
Dash	~
Dash Lights	X
The dash lights do not appear to be working, but it was a brigh They should be checked when its darker.	it day.
Dash Gauges	/
Carpet	/
Floor Mats	/
Unusual Odors	✓
Interior Trim	✓
Inner Trunk	·

Cooling Fan Condition	✓
Radiator Cap Sealing Properly	V
Hoses	✓
Radiator	✓
Engine Coolant	✓
Coolant Leaks	X
Light coolant leakage noticed.	
Belts	>
Engine Oil	>
Engine Fluid Leaks	X
The engine is seeping some oil from the underside. There were not at time of inspection. This area should be cleaned off and recheck verify source of leak or leaks.	
Transmission Fluid	V
Brake System	~
Brake Fluid Leaks	✓
Modifications	X
This is a full custom roadster show car, you little if anything left st	ock

Brake System	~
Brake Fluid Leaks	~
Modifications	X
This is a full custom roadster show car, very little if anything left sto	ock.
Road Test	
Road Test	~
Engine Performance	~
Transmission performance	~
Differential Performance	~
Wheel Bearing Performance	~
Braking Performance	~
Suspension Performance	X
Suspension type noises heard the turning and / or when going over	r
bumps.	
Steering Performance	X
The turning radius is large and may be difficult with no power steel	
tight places or parking lot manuvers. The steering wheel lightened	
once driving, unable to tell if it wanders but didn't noticed any pullir Vehicle may follow road crown.	ıg.
Engine Starting	X
Stumble noticed when cold, seemed to smooth out while warming	up.
Hard start when hot after driving for a few miles.	'
TIRES/WHEELS	
Spare Tire	X
No spare tire found with vehicle.	
Tire Manufacturer	
Driver's Front - Mastercraft Touring Lsa	
Driver's Front - Mastercraft Touring Lsa Passenger's Front - Mastercraft Touring LSA	
Ÿ	
Passenger's Front - Mastercraft Touring LSA	
Passenger's Front - Mastercraft Touring LSA Driver's Rear - Goodyear Eagle F1	
Passenger's Front - Mastercraft Touring LSA Driver's Rear - Goodyear Eagle F1 Passenger's Rear - Goodyear Eagle F1	
Passenger's Front - Mastercraft Touring LSA Driver's Rear - Goodyear Eagle F1 Passenger's Rear - Goodyear Eagle F1 Tire Size	
Passenger's Front - Mastercraft Touring LSA Driver's Rear - Goodyear Eagle F1 Passenger's Rear - Goodyear Eagle F1 Tire Size Driver's Front - 195/55R15	
Passenger's Front - Mastercraft Touring LSA Driver's Rear - Goodyear Eagle F1 Passenger's Rear - Goodyear Eagle F1 Tire Size Driver's Front - 195/55R15 Passenger's Front - 195/55R15	
Passenger's Front - Mastercraft Touring LSA Driver's Rear - Goodyear Eagle F1 Passenger's Rear - Goodyear Eagle F1 Tire Size Driver's Front - 195/55R15 Passenger's Front - 195/55R15 Driver's Rear - 245/50R16	
Passenger's Front - Mastercraft Touring LSA Driver's Rear - Goodyear Eagle F1 Passenger's Rear - Goodyear Eagle F1 Tire Size Driver's Front - 195/55R15 Passenger's Front - 195/55R15 Driver's Rear - 245/50R16 Passenger's Rear - 245/50R16	
Passenger's Front - Mastercraft Touring LSA Driver's Rear - Goodyear Eagle F1 Passenger's Rear - Goodyear Eagle F1 Tire Size Driver's Front - 195/55R15 Passenger's Front - 195/55R15 Driver's Rear - 245/50R16 Passenger's Rear - 245/50R16 Tire Condition	
Passenger's Front - Mastercraft Touring LSA Driver's Rear - Goodyear Eagle F1 Passenger's Rear - Goodyear Eagle F1 Tire Size Driver's Front - 195/55R15 Passenger's Front - 195/55R15 Driver's Rear - 245/50R16 Passenger's Rear - 245/50R16 Tire Condition Driver's Front - No Issues	
Passenger's Front - Mastercraft Touring LSA Driver's Rear - Goodyear Eagle F1 Passenger's Rear - Goodyear Eagle F1 Tire Size Driver's Front - 195/55R15 Passenger's Front - 195/55R15 Driver's Rear - 245/50R16 Passenger's Rear - 245/50R16 Tire Condition Driver's Front - No Issues Passenger's Front - No Issues	
Passenger's Front - Mastercraft Touring LSA Driver's Rear - Goodyear Eagle F1 Passenger's Rear - Goodyear Eagle F1 Tire Size Driver's Front - 195/55R15 Passenger's Front - 195/55R15 Driver's Rear - 245/50R16 Passenger's Rear - 245/50R16 Tire Condition Driver's Front - No Issues Passenger's Rear - No Issues Driver's Rear - No Issues	
Passenger's Front - Mastercraft Touring LSA Driver's Rear - Goodyear Eagle F1 Passenger's Rear - Goodyear Eagle F1 Tire Size Driver's Front - 195/55R15 Passenger's Front - 195/55R15 Driver's Rear - 245/50R16 Passenger's Rear - 245/50R16 Tire Condition Driver's Front - No Issues Passenger's Rear - No Issues Passenger's Rear - No Issues Passenger's Rear - No Issues	
Passenger's Front - Mastercraft Touring LSA Driver's Rear - Goodyear Eagle F1 Passenger's Rear - Goodyear Eagle F1 Tire Size Driver's Front - 195/55R15 Passenger's Front - 195/55R15 Driver's Rear - 245/50R16 Passenger's Rear - 245/50R16 Tire Condition Driver's Front - No Issues Passenger's Front - No Issues Driver's Rear - No Issues Passenger's Rear - No Issues Passenger's Rear - No Issues Passenger's Rear - No Issues Wheel Condition	
Passenger's Front - Mastercraft Touring LSA Driver's Rear - Goodyear Eagle F1 Passenger's Rear - Goodyear Eagle F1 Tire Size Driver's Front - 195/55R15 Passenger's Front - 195/55R15 Driver's Rear - 245/50R16 Passenger's Rear - 245/50R16 Tire Condition Driver's Front - No Issues Passenger's Front - No Issues Driver's Rear - No Issues Passenger's Front - No Issues	
Passenger's Front - Mastercraft Touring LSA Driver's Rear - Goodyear Eagle F1 Passenger's Rear - Goodyear Eagle F1 Tire Size Driver's Front - 195/55R15 Passenger's Front - 195/55R15 Driver's Rear - 245/50R16 Passenger's Rear - 245/50R16 Tire Condition Driver's Front - No Issues Passenger's Front - No Issues Passenger's Rear - No Issues Passenger's Rear - No Issues Passenger's Front - No Issues	


Tire Tread

Driver's Front - 10/32

Passenger's Front - 10/32

Driver's Rear - 8/32

Passenger's Rear - 8/32



10/32 OR MORE

Tires have plenty of tread!

(standard)

8/32 OR MORE

Tires have plenty of tread!

(low profile)

5/32 TO 7/32

Tires will need replacement soon!

4/32 OR LESS


Tires need replacement!















ANSFER OF OWNERSHIP	Seller mus	t complete this section and give title to the new owner	
on Address		Salé Date State 17an	
W Canholder Driver License or EIN 1 New Linebolder Name and Screet Address		SSSR 425 115th Date	
	77.13.000, 6012-00.002,	1.00 000	
tometer Reading (no tenths)	CI Mileage in excess of the odometer CI NOT Actual Mileage, WARNING	mechanical limits	
persity to the best of my knowledge that the adomator reading is the	he actual mileage unless one of the boxes	above is checked.	
Mer Name (printed)		Soller Signature	
Feet Address	CRy	Sale 20	
Acknow	wiedged before me this date. Notery	Public or MVD Agent Signature	
Date	County	State Commission Expris	
am aware of the above adometer certification made by the seller		· ·	
Author Authority	Buyer Signature		
EALER REASSIGNMENT			
Suyer Name (printed)		Sale Date	
Breet Address	City	State Zg	
New Limitether Differ Libertae or EIN Than Liesbolder Horse and Street Astrono	E OF NO Sees, Writte NONE)	Uses Date	
Odometer Reading (no tenths)	(3 Mileage in excess of the adometer	mechanical limits.	
☐ miles ☐ kilometers certify to the best of my knowledge that the odorwide weading is it	CI NOT Actual Mileage, WARNING -	ODOMETER DISCREPANCY.	
carnity to title best to my showledge that the outsides returning is to	Dester Number Agent Name	Agunt Signature	
am aware of the above adometer pertilication made by the seller.		4	3//
sayer Name (printed)	Buyer Signature		
EALER REASSIGNMENT Diver Name (printed)		Salt Dite	
Real Address	(Cily	State Zip	
New Lienhalter Driver License or Elly New Lientischer Name and Street Address	SE no Res, Write HONE)	Lien Diste	
A Committee of the Comm	D Mileage in excess of the odometer		
Odometer Reading (no tenths)	CLNOT Actual Mileage, WARNING -	ODGMETER DISCREPANCY.	
contify to the best of my knowledge that the odornetiff reading is to	Gesler Number Agent Name	above is checked. Agent Signature	
am aware of the above adometer cartification made by the safter		1	
Buyer Narios (printed)	Buyer Signature		**************************************
			· · · · · · · · · · · · · · · · · · ·
EALER REASSIGNMENT		Sain Date	
treat Arkfores			
	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	State Zig	
PA Controller Other Liberals Of EIN New Liberalider Name and Street Address ((6 no. 8ec, serie NOVE)	Lien Date	
Cometer Reading (no teeths)	3 Mileage in excess of the adamate	mechanical limits.	
☐ miles ☐ kilometers	CI NOT Actual Mileage WARNING-	ODOMÉTER DISGREPANCY	
certify to the best of my konstituting that the nations 4	Designation Apart Name	s above is checked. Agent Signature	
certify to the best of my knowledge that the adometal reading is the patential Nation			
on aware of the above odometry perification marie by the security			
certify to the best of my knewledge that the adometer reading is the second have. If aware of the above adometer pertilibration marks by the seller, for Name gardings.	Dilyer Signature	A Company of the Comp	



























































































































































































































































































































Note for Image 4: Copy of PA title Note for Image 5: Backside of AZ title Note for Image 6: Front side of AZ title

Note for Image 7:

Audio

Note for Image 8:

Air compressor

Note for Image 9:

Vin plate

Note for Image 14:

Air compressor and audio controls

Note for Image 17:

Cooling fan manual switch, Green LEDs and accessories switches

Note for Image 42:

LF wheel

Note for Image 43:

Mounted front tire size

Note for Image 44:

RF wheel

Note for Image 46:

Transmission fluid level and color

Note for Image 47:

Engine oil level and color

Note for Image 48:

Saturation around right cylinder head area

Note for Image 51:

Coolant pooling up below the crank dampener area

Note for Image 52:

Dripping on the ground present

Note for Image 53: Coolant pooling up below the crank dampener area Note for Image 55: Coolant pooling up below the intake area Note for Image 56: Coolant pooling up below the intake area Note for Image 57: LR wheel Note for Image 58: RR wheel Note for Image 59: mounted rear tire size Note for Image 70: Under vehicle rear Note for Image 71: Under vehicle rear

Note for Image 72:

License plate pops out when vehicle starts

Note for Image 73: RF suspension

Note for Image 74:

Exhaust cut out

Note for Image 76:

Under vehicle front

Note for Image 78:

LF suspension

Note for Image 79:

LF suspension

Note for Image 80:

RF suspension

Note for Image 81:

Under vehicle front

Note for Image 82: Hood panel gaps
Note for Image 83: Hood panel gaps
Note for Image 84: Hood panel gaps
Note for Image 85: Left reverse style door opened all the way
Note for Image 86: Paint thickness reading .90mm
Note for Image 87: Paint thickness reading .90mm
Note for Image 90: Right reverse style door opened all the way
Note for Image 93: Ignition switch under the passenger side, under dash paint chips also present
Note for Image 98: Single manual wiper arm
Note for Image 99: Single manual wiper arm
Note for Image 105: Hard to capture digital LEDs as they flash when looking through the camera
Note for Image 107: Panel gaps
Note for Image 109: Panel gaps
Note for Image 110: Panel gaps
Note for Image 111: Paint touch up
Note for Image 112: Trunk lid gaps

Note for Image 113: RF dor gaps Note for Image 114: LF lower door paint crack and gap Note for Image 117: Right door gaps Note for Image 118: Left door gaps Note for Image 119: Right door gaps Note for Image 120: RF fender paint chip Note for Image 121: Hood panel gaps Note for Image 122: Drips on ground Note for Image 123: Left door upper section paint chip Note for Image 124: LF dender paint chip Note for Image 126: Vin plate location on the right side bulk head area behind this wiring