

1967 Chrysler 300



This 1967 Chrysler 300 is in fair running and driving condition with few flaws to note.

Exterior

There are minor misc scratches around the vehicle. Most too small to see in photos. There is some minor paint chipping around the vehicle. The repaint is otherwise in good condition and shines nicely. The underside shows areas of minor surface rust. See pictures. I checked the vehicle with a paint meter and found the readings to be mostly uniform with light variations but mostly on the low end of the scale suggesting light skim coating, no excessive use of body filler or heavy areas found. All four wheels are in good condition with no curb rash or corrosion notable. The tires show 13/32nds of tread remaining, and even wear throughout.

Interior

The horn does not work. All of the other interior functions, controls, and accessories are operating as designed. There were no odd smells in the vehicle at the inspection, and this is a non-smoker vehicle. The passenger rear window crank is missing the knob. The carpet shows light wear and

discoloration from use. The inner trunk shows patch work. The rest of the interior trim and upholstery throughout the vehicle are in good condition with little to no wear to note.

Test Drive

A road test was not possible at the inspection as the water pump is leaking coolant. Due to this, I spent more time going over the vehicle. I found the engine to start and run well. The transmission engaged in both forward and reverse with no issues. The brakes were firm, and held the vehicle properly. A visual inspection of the steering and suspension showed no obvious issues. The gauges appear accurate and operational, with the exception of the speedometer as a road test was not performed. See photos and below for more information.

Vehicle Info	
Year - 1967	
Make - Chrysler	
Model - 300	
Mileage - 74874	
Transmission - Automatic	
VIN Number - cm23k76127402	
Interior - Leather	
Interior Color - Black	
Body Color - Red	
Engine - 8 Cylinder	
Drive Type - Rear Wheel Drive	
Fuel Type - Gas	
Engine Number - 440	
Transmission Number - N/A	

Exterior	
Wiper Blades	✓
Windshield Washer	✓
Body Alignment	✓
Scratches	✗
There are minor misc scratches around the vehicle. Most too small to see in photos.	
Dings	✓
Dents	✓
Paint Condition	✗
There is some minor paint chipping around the vehicle. The repaint is otherwise in good condition and shines nicely.	
Body Seals	✓
Rust	✗
The underside shows areas of minor surface rust. See pictures.	
Exterior Lights	✓
Door Mirrors	✓
Bumpers	✓
Side Moldings	✓
Frame Damage	✓
Glass	✓
Body Filler?	✗
I checked the vehicle with a paint meter and found the readings to be mostly uniform with light variations but mostly on the low end of the scale suggesting light skim coating, no excessive use of body filler or heavy areas found.	
Hood	✓
Doors	✓
Floors	✓


Mechanical	
Air Filter	✓
Battery Condition	✓
Charging System	✓
Cooling Fan Condition	✓
Radiator Cap Sealing Properly	✓
Hoses	✓
Radiator	✓
Engine Coolant	✓
Coolant Leaks	✗
The water pump is leaking coolant to a drip.	
Belts	✓
Power Steering	✓
Steering Fluid	✓
Engine Oil	✓
Engine Fluid Leaks	✓
Transmission Fluid	✓
Transmission Leaks	✓
Brake System	✓
Brake Fluid Leaks	✓
Differential leaks	✓
Muffler System	✓
CV Joints and Axles	✓
Shocks and bushings	✓
Ball Joints and Tie Rods	✓

Road Test	
Road Test	✗
A road test was not possible at the inspection as the water pump is leaking coolant.	
Engine Performance	✓
Engine Starting	✓
TIRES/WHEELS	
Spare Tire	✓
Tire Manufacturer	
Driver's Front - Mastercraft	
Passenger's Front - Mastercraft	
Driver's Rear - Mastercraft	
Passenger's Rear - Mastercraft	
Tire Size	
Driver's Front - 225/75/r14	
Passenger's Front - 225/75/r14	
Driver's Rear - 225/75/r14	

Rockers	✓
Quarter Panels	✓
Chrome	✓

Interior	
Steering Wheel	✓
Horn	✗
The horn does not work.	
Seat Condition	✓
Seat Belts	✓
Clock	✓
Radio/Navigation	✓
Inner Door Panels	✓
Window Function	✓
Dash	✓
Sun Visors	✓
Dash Lights	✓
Dash Gauges	✓
Heater	✓
Rear Defroster	✓
Carpet	✗
The carpet shows light wear and discoloration from use.	
Cigarette Use	✓
Unusual Odors	✓
Headliner	✓
Blower Motor	✓
Interior Trim	✗
The passenger rear window crank is missing the knob.	
Inner Trunk	✗
The inner trunk shows patch work.	

Passenger's Rear - 225/75/r14
Tire Condition
Driver's Front - No Issues
Passenger's Front - No Issues
Driver's Rear - No Issues
Passenger's Rear - No Issues
Wheel Condition
Driver's Front - No Issues
Passenger's Front - No Issues
Driver's Rear - No Issues
Passenger's Rear - No Issues
Tire Tread
Driver's Front - 13/32
Passenger's Front - 13/32
Driver's Rear - 13/32
Passenger's Rear - 13/32



10/32 OR MORE
Tires have plenty of tread! (standard)
8/32 OR MORE
Tires have plenty of tread! (low profile)
5/32 TO 7/32
Tires will need replacement soon!
4/32 OR LESS
Tires need replacement!

1





3





5



















































**AUTHORIZED DEALER
CERTIFICATION OF REQUIRED MAINTENANCE SERVICES**

VEHICLE DELIVERY DATE

MONTH	DATE	MILEAGE	DEALER CODE
6			
12			
18			
24			
30			

MONTH	DATE	MILEAGE	DEALER CODE
36			
42			
48			
54			
60			

The required maintenance service (see Warranty) must be certified on this form by a Chrysler Motors Corporation Authorized Dealer every six months to assure continuing coverage under manufacturer's warranty.

Use ball-point pen only to certify.





























TIE MISLOUT (COLD)				WEIGHT & MEASUREMENTS	
MODEL	FOR ALL LOADS UP TO FULL LOAD	PERMITTED FOR 5 PAIR OF LEGS	FRONT	REAR	LOAD-18
NEWPORT	28	28	24	24	1100
300 & NEW YORKER	26	26	24	24	1100
STATION WAGONS	24	24	24	28	1200

SEE OWNER'S MANUAL

5



































































