

1987 Chevrolet El Camino



1987 Chevrolet El Camino

The exterior of the vehicle overall is fair. There are minor paint flaws, scratches, and rust spots across the body. The undercarriage has plenty of rust. There is no curb rash on the wheels. There is no sign of frame damage but the hood has been removed for front-end repairs.

The Interior of the vehicle is overall good. All gauges work. All electronics are working. The radio is aftermarket and it works. The lighter works. There is a smell in the car but not necessarily from smoking. All electrical components worked.

The engine bay. I checked the fluids and the oil is good. I didn't see any visible leaks. I inspected the undercarriage for leaks and see none. I checked for rust and there is not much. All braking and suspension components appear to be good. The engine sounds good.

The vehicle starts right up with no issue. There is no smoke. The vehicle idles well. The owner did not want to move the vehicle. Overall very fair condition.

See below and pictures for more info

Vehicle Info	
Year - 1987	
Make - Chevrolet	
Model - El Camino	
Mileage - 148771	
Transmission - Automatic	
VIN Number - 3gccw80h8hs902013	
Interior - Cloth	
Interior Color - Tan	
Body Color - Tan	
Engine - 8 Cylinder	
Drive Type - Four Wheel Drive	
Fuel Type - Gas	

Exterior	
Wiper Blades	✓
Windshield Washer	✓
Body Alignment	✓
Scratches	✗
minor	
Dings	✓
Dents	✓
Paint Condition	✗
fading paint and paint spots but considering the age its in line	
Body Seals	✓
Rust	✗
minor rust	
Exterior Lights	✓
Door Mirrors	✓
Bumpers	✓
Side Moldings	✓
Frame Damage	✓
Glass	✓
Body Filler?	✓
Hood	✗
paint fading	
Doors	✓
Floors	✓
Rockers	✓
Quarter Panels	✓
Chrome	✓

Interior	
Steering Wheel	✓
Horn	✓
Seat Condition	✓
Seat Belts	✓
Radio/Navigation	✓
Inner Door Panels	✓
Power Locks	✓
Window Switches	✓
Window Function	✓
Center Console	✓
Dash	✓
Sun Visors	✓
Dash Lights	✓

Mechanical	
Air Filter	✓
Battery Condition	✓
Charging System	✓
Cooling Fan Condition	✓
Radiator Cap Sealing Properly	✓
Hoses	✓
Radiator	✓
Engine Coolant	✓
Coolant Leaks	✓
Belts	✓
Power Steering	✓
Steering Fluid	✓
Engine Oil	✓
Engine Fluid Leaks	✓
Transmission Fluid	✓
Transmission Leaks	✓
Brake System	✓
Brake Fluid Leaks	✓
Transfer Case Leaks	✓
Differential leaks	✓
Muffler System	✓
CV Joints and Axles	✓
Shocks and bushings	✓
Ball Joints and Tie Rods	✓
Modifications	✓

Road Test	
Road Test	✗
owner did not want to move it	
Engine Performance	✓
Engine Starting	✓

TIRES/WHEELS	
Spare Tire	✗
No spare tire found with vehicle.	

Tire Manufacturer	
Driver's Front - Proxes	
Passenger's Front - proxes	
Driver's Rear - proxes	
Passenger's Rear - proxes	

Tire Size	
Driver's Front - 225/40	
Passenger's Front - 225/40	
Driver's Rear - 225/40	
Passenger's Rear - 225/40	

Tire Condition	
Driver's Front - No Issues	
Passenger's Front - No Issues	
Driver's Rear - No Issues	
Passenger's Rear - No Issues	

Wheel Condition	
Driver's Front - No Issues	
Passenger's Front - No Issues	
Driver's Rear - No Issues	
Passenger's Rear - No Issues	

Dash Gauges	✓
Air Conditioning	✓
Heater	✓
Rear Defroster	✓
Carpet	✓
Floor Mats	✓
Cigarette Use	✓
Unusual Odors	✗
slight smell	
Cup Holders	✓
Headliner	✓
Blower Motor	✓
Interior Trim	✓
Inner Trunk	✓


Tire Tread

Driver's Front - 4/32

Passenger's Front - 6/32

Driver's Rear - 6/32

Passenger's Rear - 6/32



10/32 OR MORE

Tires have plenty of tread!
(standard)

8/32 OR MORE

Tires have plenty of tread!
(low profile)

5/32 TO 7/32

Tires will need replacement soon!

4/32 OR LESS

Tires need replacement!

1



2

































































































































63



















CONQUISTA















































































Note for Image 24:

rust spots

Note for Image 25:

rust

Note for Image 28:

scratch

Note for Image 29:

scratch

Note for Image 30:

scratch

Note for Image 32:

scratch

Note for Image 33:

scratch

Note for Image 36:

scratch

Note for Image 41:

scratch

Note for Image 46:

scratch

Note for Image 48:

scratch