

Date of Inspection: 12/30/2020

[Download Full-size Pictures \(.zip\)](#)
**Vehicle Inspection Report**

## Vehicle Information


Year	1970
Make	Volkswagen
Model	Volkswagen - All models
Body	
Odometer	32788

### CarDr.com Summary

Exterior is mostly fine, aside from potential issues on the Hood, Exterior Paint Condition. Interior is mostly fine, aside from potential issues on the PS Rear Carpet. Mechanical is satisfactory. Undercarriage is satisfactory. Driving Test is satisfactory.



## Reliability Score








### Vehicle History Check Summary





CarDr.com is partnered with CARFAX for all vehicle history operations.

Key:  **Satisfactory**
 **Attention Needed**
 **Unable to read**
 **Critical**

## On Board Diagnostic (OBD) Analysis

Check Engine Light Check	
Engine Misfire Monitoring	
Fuel System Monitoring	
Powertrain Electronics Monitoring	
Emissions Monitoring	

## Vehicle Fraud Check

Distance Since Code Cleared	
VIN Fraud Check Windshield	
VIN Fraud Check OBD	
VIN Fraud Check Door Panel	

\*Unable to read does not mean that an issue exists. It means that the vehicle did not support a standard OBD-II PID, its at manufacturers discretion.

## Exterior & Interior

### Exterior

#### 1 Exterior Paint



#### Condition

Paint Fade, Some runs in paint

#### 2 Hood



Rust on front nose panel.

#### 3 Driver Side Front



#### Fender

#### 4 Driver Side Front



#### Sidemarkers/Reflector

#### 5 Driver Side Front Door



#### 6 Driver Side Front Door



#### Glass

#### 7 Driver Side Front Door



#### Vent Windows

#### 8 Driver Side Door Mirror



#### 9 Driver Side Rocker



#### Panel

#### 10 Driver Side Rear Door



#### Glass

#### 11 Driver Side Rear



#### Quarter

#### 12 Driver Side Rear



#### Sidemarkers/Reflector

#### 13 Driver Side Rear Turn



#### Signal

#### 14 Driver Side Tail Lights



#### 15 Decklid/Rear Gate



#### 16 Rear Bumper



#### 17 Rear Window/Trim



### Interior

#### 1 Passenger Side Rear



#### Carpet

Wood floor

#### 2 Driver Side Front Door



#### Panel

#### 3 Driver Side Front Door



#### Controls

#### 4 Steering Wheel



#### 5 Driver Side Sun Visor



#### 6 Horn



#### 7 Driver Side Front Seat



#### 8 Driver Side Front Seat



#### Belt

#### 9 Driver Side Floor Pan



#### Weak Spots

#### 10 Dash Gauges



#### 11 Dashboard



#### 12 Radio/Navigation



#### 13 Audio Sound Level



#### 14 Blower Motor



#### 15 Climate Control Vent



#### Levers

#### 16 Heater



#### 17 Rear Defroster



#### 18 Driver Side Rear



#### Carpet

#### 19 Trim Strips



18 Passenger Side Tail	✓
Lights	
19 Passenger Side Rear	✓
Turn Signal	
20 Passenger Side Rear	✓
Quarter	
21 Passenger Side Rear	✓
Sidemarkers/Reflector	
22 Passenger Side Rear	✓
Door	
23 Passenger Side Rear	✓
Door Glass	
24 Passenger Side	✓
Rocker Panel	
25 Passenger Side Door	✓
Mirror	
26 Passenger Side Front	✓
Door	
27 Passenger Side Front	✓
Door Glass	
28 Passenger Side Front	✓
Door Vent Windows	
29 Passenger Side	✓
Sidemarkers/Reflector	
30 Passenger Side Front	✓
Turn Signal	
31 Passenger Side	✓
Headlight	
32 Grill	✓
33 Front Bumper	✓

20 Passenger Side Rear	✓
Seat	
21 Passenger Side Rear	✓
Seat Belt	
22 Passenger Side Front	✓
Door Panel	
23 Passenger Side Front	✓
Door Controls	
24 Passenger Side Front	✓
Seat	
25 Passenger Side Front	✓
Seat Belt	
26 Passenger Side Front	✓
Carpet	
27 Passenger Side Sun	✓
Visor	
28 Headliner	✓
29 Interior Odor	✓
30 Accessories	✓

34	Driver Side Front Turn	✓
Signal		
35	Driver Side Headlight	✓
36	Windshield	✓
37	Wiper Blades	✓
38	Roof	✓
39	Luggage Rack	✓
40	Body Seals	✓
41	Body Alignment	✓
42	Frame/Unibody	✓
Condition		

Mechanical	
Battery Condition	✓
Charging System	✓
Radiator Cap Sealing	✓
Hoses	✓
Radiator	✓
Engine Coolant	✓
Belts	✓
Engine Oil	✓
Inner Fender	✓
Engine	✓
Transmission Fluid	✓
Brake System	✓
Brake Fluid	✓
Transfer Case	✓
Exhaust System	✓
CV Joints and Axles	✓
Suspension	✓
Ball Joints and Tie Rods	✓
Undercarriage	✓

Road Test	
Engine Starting	✓
Engine Performance	✓
Transmission Performance	✓
Clutch	✓
Differential Performance	✓
Transfer Case	✓
Performance	
Wheel Bearing	✓
Performance	
Braking Performance	✓
Parking Brake	✓
Suspension Performance	✓
Steering Performance	✓
Tire/Wheel	
Tire Manufacturer	✓ General
Tread Depth	✓ 6/32
Tire Size	✓ 185/65/14

Idle Test
Satisfactory



Driver Side Front Tire	
Driver Side Front Wheel	
Driver Side Rear Tire	
Driver Side Rear Wheel	
Passenger Side Rear Tire	
Passenger Side Rear Wheel	
Passenger Side Front Wheel	
Spare Tire	
Passenger Side Front Tire	

Additional Inspector Notes

Front panel has some rust issues

Disclaimer

The Inspection is a parking lot inspection of a Mechanical Vehicle. The Vehicle may have been staged to hide problems and unobserved by the Inspector. The services from CarDr.com Inc are provided on an “as is” basis without warranties of any kind, either expressed or implied, including without limitation, warranties of title, non-infringement, or implied warranties of merchantability or fitness for a particular purpose.

Nothing in these terms or in any description of products or services in the services shall constitute a representation or warranty with respect to such products or services. you acknowledge, by your use of the services, that such use is at your sole risk. You agree that CarDr.com Inc's liability is limited to refunding the price you pay for the CarDr.com's inspection in the event you are dissatisfied with CarDr.com's service, or injuries occur due to an unreported defect in the vehicle. In no event shall either cardr.com or its affiliates or agents be liable for any direct, indirect, punitive, incidental, special or consequential damages arising out of or in any way connected with the use of the services, whether based on contract, tort, strict liability or otherwise, even if advised of the possibility of any such damages. By Ordering the service you agreed to the same. In the event this vehicle is from another country, warranties may not apply.





