

Vehicle Information

Year	1983
Make	Cadillac
Model	Fleetwood
VIN	1C6AB698109242021
Stock No.	N/A
Mileage	125,024
Engine Cylinders	8
Exterior Color	Blue
Interior Color	Blue
Interior Material	Leather
Engine Number	V8 4100
Transmission Number	4 speed - metric overdrive
Fuel Type	Gasoline

Drivetrain

Transmission	Automatic
Drive Type	Rear Wheel Drive

Road Test

Road Test	(Safe) Digital Fuel Injection	☒ AC Retrofit R-12 to 134
Engine Starting Easily	Yes	☒ Small Radiator leak Under Hose
Engine running well after Started	Yes	☐

Exterior

Wiper Blades

☒ New

Wipers Work

Windshield Washer

☐ Needs Repair

Body Panel Alignment

☐ Straight

Scratches

☒ Small

There are light scratches present around the exterior of the vehicle that are considered normal with age, most are too small to see in photos.

Paint Condition

☒ Good

The paint shows some wear and tear that is consistent with age and mileage.

Repainted once

Seals - Oil Pan Gasket

☒ Small leaks

Slight leak Leaking Power Steering Hose

Engine oil leak - Rear Main Seal & Valve cover

Rust

None

☒ NO Rust

Hydromatic Metric Overdrive Transmission

Exterior Lights

☒

Brakes Front - New

Power Door Mirrors

Both Work

Bumpers

☒ Good

Side Moldings

☒ Good

Underbody/Frame Condition

☒ Clean/No Rust

Glass

☒ Good

Floors

☒ Rust Free

Rockers

☒ Good

Quarter Panels

☒ Good

Body Filler Used

☒

- Air Shocks leaking (Rear)

- Exhaust Res. Rusted Bottom

Hood

☒ Good

Doors

☒ Good

- Slight play in steering idler arm (Safe to drive)

- New Front Shocks

- Older Tires (Good Condition) 2002 year Rear/2001 Front

Interior

Steering Wheel

☒ Good Condition

Horn

☒ Works

Seat Condition

☒ Good

Seat Belts

☒ Work

Clock

☒ Works/Burnt out Numbers Digital

Radio/Navigation/DVD

☒ Works

Inner Door Panels

☒ Good

Power Locks

☒ Work

Power Window Switches

☒ Work

Center Console

Arm Rest Good Condition

Dash

☒ Good - Carpet Dash Mat

Dash Lights Working

☒ Yes

Air Conditioning

☒ Electronic Climate Control

- Works (Fan Running) low Freon

Heater

☒ Works

Carpet

☒ Good

Floor Mats

☒ Fronts Missing

Signs of Smoking?

☒ NO

Headliner

☒ Good

Auto Trunk Release Works

Blower Motor

☒ Works Clock #5 Burnt Digital 1

Instrument Cluster/Gauges

☒ Works Doesnt Work

Unusual Odors

☒ NO

Window Function

☒ Yes

Interior Trim

☒ Good

One small crack in Chrome insert door panel

Doors	☒ Good
Dings	☒ None
Dents	☒ None
Chrome	☒ Good

Vinyl Top - Good Condition
 Engine Belts - New