

## 1965 Ford F100



### Summary

This 1965 Ford F100 ran and drove well. It has a 352 v-8. This truck has a six and a half foot bed. The headlights and taillights are functional. On the exterior I noted there are minor misc scratches around the vehicle. Most too small to see in photos. There is a small amount of body imperfection on driver's side rear fender.

Inside I noted there is light wear to the seats. The interior trim looked good overall. I noted no smoke or odd odors. The windows went up and down. The gauges worked. The heater and blower functioned.

Under the hood I noted full accessible fluids. There were no visual engine bay leaks.

I found no issues on the test drive. The engine had plenty of power and there were no misfires or smoking. The transmission worked as designed. The steering and the suspension worked well for the age of the vehicle. There were no abnormal vibrations or odd noises. The brakes were firm with no pulsation felt. There were no leaks found to the underside of the vehicle.

See below and pictures for more info.











## Vehicle Information

Year	1965
Make	Ford
Model	F100
VIN	F10DL657898
Stock No.	00000
Mileage	31456
Interior Color	Blue
Interior Material	Vinyl
Engine Cylinders	8 Cylinder
Exterior Color	Blue
Engine Number	N/A
Transmission Number	N/A
Fuel Type	Gas





















## Drivetrain

Transmission	Manual
Drive Type	Rear Wheel Drive

## Road Test

Road Test	 Good
Engine Starting Easily	 Good
Engine running well after Started	 Good
Transmission performance	 Good
Clutch Performance	 Good
Differential Performance	 Good
Wheel Bearing Performance	 Good
Braking Performance	 Good
Suspension Performance	 Good
Steering Performance and Alignment	 Good






















## Exterior

Wiper Blades	 Good
Windshield Washer	 Good
Body Panel Alignment	 Good
Scratches	 Issues
There are minor misc scratches around the vehicle. Most too small to see in photos.	
Paint Condition	 Issues
There is a small amount of body imperfection on driver's side rear fender.	
Seals	 Good
Rust	 Good
Exterior Lights	 Good
Power Door Mirrors	 Good
Bumpers	 Good
Side Moldings	 Good
Underbody/Frame Condition	 Good
Glass	 Good
Floors	 Good
Rockers	 Good
Quarter Panels	 Good
Body Filler Used	 Good
Hood	 Good
Doors	 Good
Chrome	 Good

## Interior

Steering Wheel	 Good
Horn	 Good
Seat Condition	 Issues
There is light wear to the seats.	
Seat Belts	 Good
Clock	 Good
Radio/Navigation/DVD	 Good
Inner Door Panels	 Good
Dash	 Good
Dash Lights Working	 Good
Heater	 Good
Carpet	 Good
Floor Mats	 Good
Cup Holders	 Good
Headliner	 Good
Blower Motor	 Good
Instrument Cluster/Gauges	 Good
Unusual Odors	 Good
Window Function	 Good
Interior Trim	 Good
Sun Visors	 Good

## Mechanical

Air Filter	 Good
Battery Condition	 Good
Charging System	 Good
Cooling Fan Condition Mechanical/Electronic	 Good
Hoses and Clamps Age/Cracking	 Good
Radiator Condition	 Good
Engine Coolant Condition	 Good
Belts	 Good
Power Steering System	 Good
Power Steering Fluid Condition	 Good
Engine Oil Condition	 Good
Engine Oil Leaks	 Good
Brake System Condition	 Good
Brake Fluid Leaks	 Good
Differential leaks	 Good
Muffler System	 Good
CV Boots and Joints	 Good
Shocks and bushings Condition. Leaking?	 Good
Ball Joints and Tie Rods	 Good
Radiator Cap Sealing Properly	 Good
Coolant Leaks	 Good

## Tire / Wheels

Manufacturer	
Driver's Front Tire	Goodyear
Passenger's Front Tire	Goodyear
Driver's 1st Axle Outer Tire	Goodyear
Passenger's 1st Axle Outer Tire	Goodyear
Size	
Driver's Front Tire	235/75R15
Passenger's Front Tire	235/75R15
Driver's 1st Axle Outer Tire	235/75R15
Passenger's 1st Axle Outer Tire	235/75R15
Tire Condition	
Driver's Front Tire	No Issues
Passenger's Front Tire	No Issues
Driver's 1st Axle Outer Tire	No Issues
Passenger's 1st Axle Outer Tire	No Issues
Wheel Condition	
Driver's Front Tire	No Issues
Driver's 1st Axle Outer Tire	No Issues
Passenger's Front Tire	No Issues
Passenger's 1st Axle Outer Tire	No Issues
Tire Tread	
Driver's Front Tire	10/32
Passenger's Front Tire	12/32
Driver's 1st Axle Outer Tire	12/32
Passenger's 1st Axle Outer Tire	12/32
Spare Tire	
	Yes



## Vehicle Images







































WARRANTY VOID IF MAX. GROSS VEHICLE WEIGHT IS EXCEEDED  
(SEE OPERATOR'S MANUAL FOR LOAD CAPACITY CHART)

F10DL657898



REG. IN  
STATE OF

NOT FOR TITLE OR REGISTRATION PURPOSES

W.B. COLORADO BODY TRANS AXLE

115 W F100 281 A 08

MAX. G.V.W. LBS. NET H.P. R.P.M. D.S.O.

5000 172 4000 641550


WARRANTY VOID IF MAX. GROSS VEHICLE WEIGHT IS EXCEEDED  
(SEE OPERATOR'S MANUAL FOR LOAD CAPACITY CHART)







































































































































































































Explore maintenance, repair and inspection services here.



Lemon

Squad

Nationwide Used Car Inspection



WRENCH