

Date of Inspection: 12/9/2020

[Download Full-size Pictures \(zip\)](#)

Vehicle Inspection Report

Vehicle Information

Year	1969
Make	Dodge
Model	Coronet
Body	2 Door
Odometer	77433

CarDr.com Summary

Exterior has multiple potential issues. Interior has multiple potential issues. Mechanical is mostly fine, aside from potential issues on the Exhaust System. Undercarriage is satisfactory. Accessories have potential issues. Accessories. Driving Test was mostly fine, aside from potential issues on the Transmission Performance, Engine Starting.



Vehicle History Check Summary





CarDr.com is partnered with CARFAX for all vehicle history operations. For a full CARFAX VHR, [order here](#)

CarDr.com AI Suggested Fair Market Value






[Order Now](#)

CarDr.com Verbal Assesment





[Order Now](#)

Key:  Satisfactory  Attention Needed  Unable to read  Critical

On Board Diagnostic (OBD) Analysis

Check Engine Light Check	
Engine Misfire Monitoring	
Fuel System Monitoring	
Powertrain Electronics Monitoring	
Emissions Monitoring	

Vehicle Fraud Check



Distance Since Code Cleared	
VIN Fraud Check Windshield	
VIN Fraud Check OBD	
VIN Fraud Check Door Panel	

*Unable to read does not mean that an issue exists. It means that the vehicle did not support a standard OBD-II PID, its at manufacturers discretion.



*Distance since Codes Cleared can be the number of miles since a recent repair. Please ask seller for details.



























Exterior & Interior























Exterior

- Exterior Paint Condition  PaintFade
- Body Alignment  Minimal Misalignment

Interior

- Accessories  Aftermarket radio
- Interior Odor  gasoline odor


3	Body Seals		Dried Out
4	Roof		Light Scratch ,Deep Scratch
5	Hood		Light Scratch ,Misaligned
6	Front Bumper		Light Scratch
7	Passenger Side Front Fender		Light Scratch
8	Passenger Side Front Door Vent Windows		Pitted
9	Passenger Side Front Door		Light Scratch
10	Passenger Side Door Mirror		Chrome Peel
11	Passenger Side Rocker Panel		Paint Fade
12	Passenger Side Rear Quarter		Previous Repair
13	Rear Window/Trim		Broke
14	Decklid/Rear Gate		Missing Weather Strip
15	Driver Side Rear Quarter		Light Scratch
16	Driver Side Rear Door Glass		Scratched
17	Driver Side Rocker Panel		Light Scratch
18	Driver Side Door Mirror		Pitted
19	Driver Side Front Door Vent Windows		Pitted
20	Driver Side Front Door		Paint Chips
21	Driver Side Front Sidemarker/Reflector		Missing
22	Driver Side Front Fender		Light Scratch ,Deep Scratch
23	Driver Side Front Door Glass		
24	Driver Side Rear Sidemarker/Reflector		
25	Driver Side Rear Turn Signal		
26	Driver Side Tail Lights		
27	Trunk Pan		
28	Rear Bumper		

3	Headliner		Wear
4	Passenger Side Rear Door Panel		Missing armrest
5	Heater		Inop
6	Driver Side Front Carpet		Wear
7	Steering Wheel		Cracks
8	Driver Side Front Door Panel		Stained
9	Driver Side Front Door Controls		
10	Driver Side Sun Visor		
11	Horn		
12	Driver Side Front Seat		
13	Driver Side Front Seat Controls		
14	Driver Side Front Seat Belt		
15	Driver Side Floor Pan Weak Spots		
16	Dash Gauges		
17	Radio/Navigation		
18	Audio Sound Level		
19	Driver Side Rear Door Panel		
20	Driver Side Rear Seat		
21	Driver Side Rear Seat Belt		
22	Driver Side Rear Carpet		
23	Passenger Side Rear Seat		
24	Passenger Side Rear Seat Belt		

Mechanical	Road Test
Exhaust System	Engine Starting
Air Filter	Transmission Performance
Battery Condition	Differential Performance
Charging System	Wheel Bearing Performance
Cooling Fan Condition	Braking Performance
Radiator Cap Sealing	Parking Brake
Hoses	Suspension Performance
Radiator	Steering Performance
Engine Coolant	
Water Pump	Tire/Wheel
Belts	Tire Manufacturer
Power Steering	Tread Depth
Engine Oil	Tire Size
Inner Fender	Driver Side Front Tire
Firewall	
Shock Towers	

Carburetor	✓
Engine Covers	✓
Engine	✓
Transmission Fluid	✓
Brake System	✓
Brake Fluid	✓
Differential	✓
CV Joints and Axles	✓
Suspension	✓
Ball Joints and Tie Rods	✓
Key Fob/Key	✓
Undercarriage	✓

Test Drive Details

 Test Drive Start Time (EST): 2020-12-09 17:39:47

 City Location: 8361 SE Page St, Hobe Sound, FL 33455, USA

Idle Test

Satisfactory ✓

Driver Side Front Wheel	✓
Driver Side Rear Tire	✓
Driver Side Rear Wheel	✓
Passenger Side Rear Tire	✓
Passenger Side Rear Wheel	✓
Passenger Side Front Tire	✓

Additional Inspector Notes

318-V8 automatic transmission car is in original condition but very far from being perfect the hood is out of alignment there are scratches and scrapes on every body panel.

Disclaimer

The Inspection is a parking lot inspection of a Mechanical Vehicle. The Vehicle may have been staged to hide problems and unobserved by the Inspector. The services from CarDr.com Inc are provided on an "as is" basis without warranties of any kind, either expressed or implied, including without limitation, warranties of title, non-infringement, or implied warranties of merchantability or fitness for a particular purpose.

Nothing in these terms or in any description of products or services in the services shall constitute a representation or warranty with respect to such products or services. you acknowledge, by your use of the services, that such use is at your sole risk. You agree that CarDr.com Inc's liability is limited to refunding the price you pay for the CarDr.com's inspection in the event you are dissatisfied with CarDr.com's service, or injuries occur due to an unreported defect in the vehicle. In no event shall either cardr.com or its affiliates or agents be liable for any direct, indirect, punitive, incidental, special or consequential damages arising out of or in any way connected with the use of the services, whether based on contract, tort, strict liability or otherwise, even if advised of the possibility of any such damages. By Ordering the service you agreed to the same. In the event this vehicle is from another country, warranties may not apply.



