

Date of Inspection: 8/28/2021

[Download Full-size Pictures \(zip\)](#)

Vehicle Inspection Report

### Vehicle Information

|          |               |
|----------|---------------|
| Year     | 1963          |
| Make     | Mercedes Benz |
| Model    | 190SL         |
| Body     | 2 Door        |
| Odometer | 152           |



### Reliability Score



### Vehicle History Check Summary

CarDr.com is partnered with CARFAX for all vehicle history operations.






Key:  Satisfactory

 Attention Needed





 Unable to read

 Critical

### On Board Diagnostic (OBD) Analysis

|                                   |   |
|-----------------------------------|---|
| Check Engine Light Check          |  |
| Engine Misfire Monitoring         |  |
| Fuel System Monitoring            |  |
| Powertrain Electronics Monitoring |  |
| Emissions Monitoring              |  |

### Vehicle Fraud Check

|                             |   |
|-----------------------------|---|
| Distance Since Code Cleared |  |
| VIN Fraud Check Windshield  |  |
| VIN Fraud Check OBD         |  |
| VIN Fraud Check Door Panel  |  |

\*Unable to read does not mean that an issue exists. It means that the vehicle did not support a standard OBD-II PID, its at manufacturers discretion.

\*Distance since Codes Cleared can be the number of miles since a recent repair. Please ask seller for details.

| Exterior & Interior               |                                 |  |
|-----------------------------------|---------------------------------|--|
| Exterior                          |                                 |  |
| 1 Exterior Paint                  | !                               |  |
| Condition                         | total repaint -acceptable paint |  |
| 2 Hood                            | !                               |  |
|                                   | Ding                            |  |
| 3 Grill                           | !                               |  |
|                                   | dent                            |  |
| 4 Passenger Side Front Fender     | !                               |  |
|                                   | Ding ,Paint Chips               |  |
| 5 Passenger Side Front Door       | !                               |  |
|                                   | Paint Chips                     |  |
| 6 Passenger Side Door Mirror      | !                               |  |
|                                   | missing                         |  |
| 7 Passenger Side Rear Quarter     | !                               |  |
|                                   | Rust                            |  |
| 8 Passenger Side Tail Lights      | !                               |  |
|                                   | Cracked                         |  |
| 9 Driver Side Tail Lights         | !                               |  |
|                                   | Cracked                         |  |
| 10 Driver Side Rear Quarter       | !                               |  |
|                                   | Deep Scratch                    |  |
| 11 Driver Side Rocker Panel       | !                               |  |
|                                   | Paint Chips                     |  |
| 12 Driver Side Front Door         | !                               |  |
|                                   | Paint Chips                     |  |
| 13 Driver Side Front Fender       | !                               |  |
|                                   | Paint Chips                     |  |
| 14 Driver Side Front Door Glass   | ✓                               |  |
| 15 Driver Side Door Mirror        | ✓                               |  |
|                                   |                                 |  |
| Interior                          |                                 |  |
| 1 Audio Sound Level               | !                               |  |
|                                   | ,No Audio                       |  |
| 2 Radio/Navigation                | !                               |  |
|                                   | ,Inop                           |  |
| 3 Steering Wheel                  | !                               |  |
|                                   | Cracks                          |  |
| 4 Driver Side Front Door Panel    | ✓                               |  |
| 5 Driver Side Sun Visor           | ✓                               |  |
| 6 Horn                            | ✓                               |  |
| 7 Driver Side Front Seat          | ✓                               |  |
| 8 Driver Side Front Seat Belt     | ✓                               |  |
| 9 Driver Side Front Carpet        | ✓                               |  |
| 10 Driver Side Floor Pan          | ✓                               |  |
| Weak Spots                        |                                 |  |
| 11 Dash Gauges                    | ✓                               |  |
| 12 Dashboard                      | ✓                               |  |
| 13 Clock                          | ✓                               |  |
| 14 Center Console                 | ✓                               |  |
| 15 Driver Side Rear Carpet        | ✓                               |  |
| 16 Trim Strips                    | ✓                               |  |
| 17 Passenger Side Rear Carpet     | ✓                               |  |
| 18 Passenger Side Front Seat      | ✓                               |  |
| 19 Passenger Side Front Seat Belt | ✓                               |  |

|                           |   |
|---------------------------|---|
| 16 Driver Side Side       | ✓ |
| Moldings                  |   |
| 17 Driver Side Rear Turn  | ✓ |
| Signal                    |   |
| 18 Decklid/Rear Gate      | ✓ |
| 19 Trunk Pan              | ✓ |
| 20 Rear Bumper            | ✓ |
| 21 Passenger Side Rear    | ✓ |
| Turn Signal               |   |
| 22 Passenger Side Side    | ✓ |
| Moldings                  |   |
| 23 Passenger Side         | ✓ |
| Rocker Panel              |   |
| 24 Passenger Side Front   | ✓ |
| Door Glass                |   |
| 25 Passenger Side Front   | ✓ |
| Turn Signal               |   |
| 26 Passenger Side         | ✓ |
| Headlight                 |   |
| 27 Front Bumper           | ✓ |
| 28 Driver Side Front Turn | ✓ |
| Signal                    |   |
| 29 Driver Side Headlight  | ✓ |
| 30 Windshield             | ✓ |
| 31 Wiper Blades           | ✓ |
| 32 Roof                   | ✓ |
| 33 Convertible Top        | ✓ |
| 34 Body Seals             | ✓ |
| 35 Body Alignment         | ✓ |
| 36 Frame/Unibody          | ✓ |
| Condition                 |   |

|                         |   |
|-------------------------|---|
| 20 Passenger Side Front | ✓ |
| Carpet                  |   |
| 21 Passenger Side Floor | ✓ |
| Pan Weak Spots          |   |
| 22 Floor Mats           | ✓ |
| 23 Passenger Side Sun   | ✓ |
| Visor                   |   |
| 24 Headliner            | ✓ |
| 25 Interior Odor        | ✓ |

| Mechanical               |   |
|--------------------------|---|
| Key Fob/Key              | ✓ |
| Exhaust System           | ✓ |
| Differential             | ✓ |
| Brake Fluid              | ✓ |
| Transmission Fluid       | ✓ |
| Firewall                 | ✓ |
| Inner Fender             | ✓ |
| Engine Oil               | ✓ |
| Carburetor               | ✓ |
| Air Filter               | ✓ |
| Battery Condition        | ✓ |
| WindShield Washer        | ✓ |
| Charging System          | ✓ |
| Cooling Fan Condition    | ✓ |
| Radiator Cap Sealing     | ✓ |
| Hoses                    | ✓ |
| Engine Coolant           | ✓ |
| Radiator                 | ✓ |
| Water Pump               | ✓ |
| Belts                    | ✓ |
| Power Steering           | ✓ |
| Steering Fluid           | ✓ |
| CV Joints and Axles      | ✓ |
| Suspension               | ✓ |
| Ball Joints and Tie Rods | ✓ |
| Brake System             | ✓ |
| Engine                   | ✓ |
| Undercarriage            | ✓ |
| Idle Test                |   |
| Satisfactory             | ✓ |

| Road Test                  |  |
|----------------------------|--|
| Engine Performance         | <div><div>⚠</div><div>rough idle</div></div> |
| Engine Starting            | <div><div>✓</div></div>                      |
| Transmission Performance   | <div><div>✓</div></div>                      |
| Clutch                     | <div><div>✓</div></div>                      |
| Differential Performance   | <div><div>✓</div></div>                      |
| Wheel Bearing Performance  | <div><div>✓</div></div>                      |
| Braking Performance        | <div><div>✓</div></div>                      |
| Parking Brake              | <div><div>✓</div></div>                      |
| Suspension Performance     | <div><div>✓</div></div>                      |
| Steering Performance       | <div><div>✓</div></div>                      |
|                            |  |
| Tire/Wheel                 |  |
| Passenger Side Front Tire  | <div><div>⚠</div><div>8/32nds</div></div>    |
| Passenger Side Rear Tire   | <div><div>⚠</div><div>9/32nds</div></div>    |
| Driver Side Rear Tire      | <div><div>⚠</div><div>9/32ndd</div></div>    |
| Driver Side Front Tire     | <div><div>⚠</div><div>8/32ndd</div></div>    |
| Tire Manufacturer          | <div><div>✓</div><div>kingstar</div></div>   |
| Tread Depth                | <div><div>✓</div></div>                      |
| Tire Size                  | <div><div>✓</div><div>185/80R13</div></div>  |
| Driver Side Front Wheel    | <div><div>✓</div></div>                      |
| Driver Side Rear Wheel     | <div><div>✓</div></div>                      |
| Passenger Side Rear Wheel  | <div><div>✓</div></div>                      |
| Passenger Side Front Wheel | <div><div>✓</div></div>                      |
| Spare Tire                 | <div><div>✓</div></div>                      |



## Additional Inspector Notes

vehicle drives good went through all gears with no issues .

## Disclaimer

The Inspection is a parking lot inspection of a Mechanical Vehicle. The Vehicle may have been staged to hide problems and unobserved by the Inspector. The services from CarDr.com Inc are provided on an "as is" basis without warranties of any kind, either expressed or implied, including without limitation, warranties of title, non-infringement, or implied warranties of merchantability or fitness for a particular purpose.

Nothing in these terms or in any description of products or services in the services shall constitute a representation or warranty with respect to such products or services. you acknowledge, by your use of the services, that such use is at your sole risk. You agree that CarDr.com Inc's liability is limited to refunding the price you pay for the CarDr.com's inspection in the event you are dissatisfied with CarDr.com's service, or injuries occur due to an unreported defect in the vehicle. In no event shall either cardr.com or its affiliates or agents be liable for any direct, indirect, punitive, incidental, special or consequential damages arising out of or in any way connected with the use of the services, whether based on contract, tort, strict liability or otherwise, even if advised of the possibility of any such damages. By Ordering the service you agreed to the same. In the event this vehicle is from another country, warranties may not apply.


























ISD 83 VR (REV. 1/2017)  
STATE OF CALIFORNIA  
**DMV**  
DEPARTMENT OF MOTOR VEHICLES  
A Public Service Agency

**VEHICLE REGISTRATION**

| VIN             | MAKE | YEAR |
|-----------------|------|------|
| 121042100227750 | MERZ | 1966 |

**To renew, just provide:**

UTI AUTO 07/08/2017

















