

1991 Jaguar XJS



This vehicle looks to have been well kept with minor issues of note. I found no obvious signs of the vehicle having prior major accident or flood damage. There are minor misc. scratches around the vehicle. Normal for mileage and most too small to see in photos. There is a minor ding on the left door. Acid burns from battery exploding in another vehicle. The paint shows some wear and tear that is consistent with age and mileage. The underside shows areas of minor surface rust. See pictures. The exterior shows wear with what is considered to be appropriate for the age and mileage of the vehicle.

The interior shows well with only light wear noted. There is light wear to the seats. Normal for mileage. The inner door panels show wear consistent with age and mileage. The interior trim shows normal wear consistent with age and mileage. The carpet shows normal wear consistent with age and mileage. The speedometer works good until 40mph, and then it sticks at 40mph. All accessories are working as designed.

I found no issues on the test drive. The engine had plenty of power and there were no misfires. The transmission shifted as designed with no harsh engagement or slipping. The steering was responsive and the suspension was firm and the vehicle handled well. There were no abnormal

vibrations or odd noises. The brakes were firm with no pulsation felt. There were no leaks found to the underside of the vehicle. I hooked up my Scan Tool to the computer system and found no current or pending codes. All of the live data looked good with no issues reported. See below and pictures for more info.

Vehicle Info	
Year - 1991	
Make - Jaguar	
Model - XJS	
Mileage - 80321	
Transmission - Automatic	
VIN Number - Sajtw4846mc177135	
Stock Number - NA	
Interior - Leather	
Interior Color - Tan	
Body Color - White	
Engine - 12 Cylinder	
Drive Type - Rear Wheel Drive	
Fuel Type - Gas	

Exterior	
Wiper Blades	✓
Windshield Washer	✓
Body Alignment	✓
Scratches	✗
There are minor misc scratches around the vehicle. Normal for mileage and most too small to see in photos.	
Dings	✗
There is a minor ding on the left door.	
Dents	✓
Paint Condition	✗
Acid burns from battery exploding in another vehicle. The paint shows some wear and tear that is consistent with age and mileage.	
Body Seals	✓
Rust	✗
The underside shows areas of minor surface rust. See pictures.	
Exterior Lights	✓
Door Mirrors	✓
Bumpers	✓
Side Moldings	✓
Convertible Top	✓
Frame Damage	✓
Glass	✓
Body Filler?	✓
Hood	✓
Doors	✓
Floors	✓
Rockers	✓
Quarter Panels	✓
Chrome	✓

Interior	
Steering Wheel	✓
Horn	✓
Cruise Control	✓
Seat Condition	✗
There is light wear to the seats. Normal for mileage.	
Heated Seats	✓

Mechanical	
Air Filter	✓
Battery Condition	✓
Charging System	✓
Cooling Fan Condition	✓
Radiator Cap Sealing Properly	✓
Hoses	✓
Radiator	✓
Engine Coolant	✓
Coolant Leaks	✓
Belts	✓
Power Steering	✓
Steering Fluid	✓
Engine Oil	✓
Engine Fluid Leaks	✓
Transmission Fluid	✓
Transmission Leaks	✓
Brake System	✓
Brake Fluid Leaks	✓
Differential leaks	✓
Muffler System	✓
CV Joints and Axles	✓
Shocks and bushings	✓
Ball Joints and Tie Rods	✓

Road Test	
Road Test	✓
Engine Performance	✓
Transmission performance	✓
Differential Performance	✓
Wheel Bearing Performance	✓
Braking Performance	✓
Suspension Performance	✓
Steering Performance	✓
Engine Starting	✓

TIRES/WHEELS	
Spare Tire	✓


Tire Manufacturer	
Driver's Front - Firestone	
Passenger's Front - Firestone	
Driver's Rear - Firestone	
Passenger's Rear - Firestone	

Tire Size	
Driver's Front - 235/60r15	
Passenger's Front - 235/60r15	
Driver's Rear - 235/60r15	
Passenger's Rear - 235/60r15	

Tire Condition	
Driver's Front - No Issues	
Passenger's Front - No Issues	
Driver's Rear - No Issues	

Seat Belts	✓
Clock	✓
Radio/Navigation	✓
Inner Door Panels	✗
The inner door panels show wear consistent with age and mileage.	
Power Locks	✓
Window Switches	✓
Window Function	✓
Center Console	✓
Dash	✓
Sun Visors	✓
Dash Lights	✓
Dash Gauges	✗
The speedometer works good until 40mph, and then it sticks at 40mph.	
Air Conditioning	✓
Heater	✓
Rear Defroster	✓
Carpet	✗
The carpet shows normal wear consistent with age and mileage.	
Floor Mats	✓
Cigarette Use	✓
Unusual Odors	✓
Cup Holders	✓
Headliner	✓
Blower Motor	✓
Interior Trim	✗
The interior trim shows normal wear consistent with age and mileage.	
Inner Trunk	✓

Passenger's Rear - No Issues
Wheel Condition
Driver's Front - No Issues
Passenger's Front - No Issues
Driver's Rear - No Issues
Passenger's Rear - No Issues
Tire Tread
Driver's Front - 10/32
Passenger's Front - 10/32
Driver's Rear - 10/32
Passenger's Rear - 10/32



10/32 OR MORE

Tires have plenty of tread!
(standard)

8/32 OR MORE

Tires have plenty of tread!
(low profile)

5/32 TO 7/32

Tires will need replacement soon!

4/32 OR LESS

Tires need replacement!

1



2



STATE OF OKLAHOMA

3

VEHICLE IDENTIFICATION NUMBER
SAJTW4846MC177135

YEAR
1991

MAKE
JAGU

TITLE NO.
552491119008E

BODY TYPE
CV

MODEL
XCC

DATE 1st SOLD

DATE ISSUED
09/21/2012

AGENT NO.
5911


ODOMETER

TYPE OF TITLE
TRANSFER

EXEMPT

DATE INS.
LOSS OR SALVAGE

NAME AND ADDRESS OF VEHICLE OWNER



EARK KESNER
4407 E 46TH ST
TULSA

OK 74135-4724

THIS VEHICLE IS SUBJECT TO THE FOLLOWING LIEN(S):

It is hereby certified that according to the records of the Oklahoma Tax Commission, the person named hereon is the owner of the vehicle described above which is subject to a lien(s) as shown; however, the vehicle may be subject to other liens or security interests.

CONTROL NO.

122655911A1023

37314202

(This is not a title number)



CERTIFICATE OF TITLE

STATE OF OKLAHOMA

VEHICLE IDENTIFICATION NUMBER

SAJTW4846MC177135

YEAR

1991

MAKE

JAGU

TITLE NO.

552491119008E

BODY TYPE

CV

MODEL

XCC

DATE 1st SOLD

DATE ISSUED

09/21/2012

AGENT NO.


5911

ODOMETER

EXEMPT

TYPE OF TITLE
TRANSFERDATE INS.
LOSS OR SALVAGE

NAME AND ADDRESS OF VEHICLE OWNER



EARK KESNER

4407 E 46TH ST

TULSA

OK 74135-4724

THIS VEHICLE IS SUBJECT TO THE FOLLOWING LIEN(S):

CERTIFICATE OF TITLE

STATE OF OKLAHOMA

VEHICLE IDENTIFICATION NUMBER

SAJTW4846MC177135

YEAR

1991

MAKE

JAGU

TITLE NO.

552491119008E

BODY TYPE

CV

MODEL

XCC

DATE 1st SOLD

DATE ISSUED

09/21/2012

AGENT NO.

5911

ODOMETER


TYPE OF TITLE

TRANSFER

EXEMPT

DATE INS.
LOSS OR SALVAGE

NAME AND ADDRESS OF VEHICLE OWNER



EARK KESNER

4407 E 46TH ST

TULSA

OK 74135-4724

THIS VEHICLE IS SUBJECT TO THE FOLLOWING LIEN(S):

It is hereby certified that according to the records of the Oklahoma Tax Commission, the person named hereon is the owner of the vehicle described above which is subject to a lien(s) as shown; however, the vehicle may be subject to other liens or security interests.

CONTROL NO. 122655911A1023

37314202

(This is not a title number)









9

































































































































































































SAJTW4846MC177135

MADE IN ENGLAND

























MFD BY JAGUAR CARS LTD. COVENTRY ENGLAND

MFD DATE

10/90

GVWR

4710LB

GAWR F

2420LB

R

2290LB

THIS VEHICLE CONFORMS TO ALL APPLICABLE
FEDERAL MOTOR VEHICLE SAFETY BUMPER AND
THEFT PREVENTION STANDARDS IN EFFECT ON
THE DATE OF MANUFACTURE SHOWN ABOVE.

VEH IDENT NO

SAJTW4846MC177135

TYPE

PASSENGER CAR

PAINT

NDP

TRIM

AEE

PART No
CBC 2830



























Note for Image 18:

LH door ding

Note for Image 35:

Odometer after test drive

Note for Image 46:

Acid burns

Note for Image 47:

Acid burns

Note for Image 112:

Odometer before test drive

Note for Image 117:

Vin

Note for Image 123:

Acid burns

Note for Image 124:

Acid burns