

1958 Ford Thunderbird



This Ford ran and drove well with some other issues of note. There was no video available for this inspection. On the exterior I noted the body of the vehicle everything aligns good including the doors, hood, and trunk. There are minor misc scratches around the vehicle. Most too small to see in photos. The underside and engine bay show areas of some surface rust. I checked the vehicle with a magnet and found it to stick all around but was weaker in the lower panels. Not excessive.

Inside I noted light wear on the seats. The door panels and interior trim looked good overall. I noted no smoke or odd odors. The interior blower worked, but I noted no heat. The windows and gauges worked.

Under hood I noted the vehicle shows signs of oil leak on top of the engine. The engine shows active oil leaks. The engine should be pressure washed off and rechecked to verify source of the leak or all leaks. I noted some rust on the underside of the hood.

I found no issues on the test drive. The engine had plenty of power and there were no misfires or smoking. The transmission shifted as designed with no harsh engagement or slipping. The steering was responsive and the suspension was firm and the vehicle handled well. There were no abnormal

vibrations or odd noises. The brakes were firm with no pulsation felt.

See below and pictures for more info.

Vehicle Info	
Year - 1958	
Make - Ford	
Model - Thunderbird	
Mileage - 61945	
Transmission - Automatic	
VIN Number - h8yh106773	
Interior - Leather	
Interior Color - Black	
Body Color - Black	
Engine - 8 Cylinder	
Drive Type - Rear Wheel Drive	
Fuel Type - Gas	

Exterior	
Wiper Blades	✓
Windshield Washer	✓
Body Alignment	✓
Scratches	✗
There are minor misc scratches around the vehicle. Most too small to see in photos.	
Dings	✓
Dents	✓
Paint Condition	✓
Body Seals	✓
Rust	✗
The underside and engine bay show areas of some surface rust. I noted some rust on the underside of the hood.	
Exterior Lights	✓
Door Mirrors	✓
Bumpers	✓
Side Moldings	✓
Frame Damage	✓
Glass	✓
Body Filler?	✗
I checked the vehicle with a magnet and found it to stick all around but was weaker in the lower panels. Not excessive.	
Hood	✓
Doors	✓
Floors	✓
Rockers	✓
Quarter Panels	✓
Chrome	✓

Interior	
Steering Wheel	✓
Horn	✓
Seat Condition	✗
There is light wear to the seats.	
Clock	✓
Radio/Navigation	✓
Inner Door Panels	✓
Power Locks	✓
Window Switches	✓


Mechanical	
Air Filter	✓
Battery Condition	✓
Charging System	✓
Cooling Fan Condition	✓
Radiator Cap Sealing Properly	✓
Hoses	✓
Radiator	✓
Engine Coolant	✓
Coolant Leaks	✓
Belts	✓
Power Steering	✓
Steering Fluid	✓
Engine Oil	✓
Engine Fluid Leaks	✗
The vehicle shows signs of oil leak on top of the engine. The engine shows active oil leaks. The engine should be pressure washed off and rechecked to verify source of the leak or all leaks.	
Transmission Fluid	✓
Transmission Leaks	✓
Brake System	✓
Brake Fluid Leaks	✓
Differential leaks	✓
Muffler System	✓
CV Joints and Axles	✓
Shocks and bushings	✓
Ball Joints and Tie Rods	✓
Modifications	✓

Road Test	
Road Test	✓
Engine Performance	✓
Transmission performance	✓
Differential Performance	✓
Wheel Bearing Performance	✓
Braking Performance	✓
Suspension Performance	✓
Steering Performance	✓
Engine Starting	✓

TIRES/WHEELS	
Spare Tire	✓
Tire Manufacturer	
Driver's Front - Supreme Classic	
Passenger's Front - Supreme Classic	
Driver's Rear - Supreme Classic	
Passenger's Rear - Supreme Classic	
Tire Size	
Driver's Front - 800 x 14, 2-1/4	
Passenger's Front - 800 x 14, 2-1/4	
Driver's Rear - 800 x 14, 2-1/4	
Passenger's Rear - 800 x 14, 2-1/4	
Tire Condition	
Driver's Front - No Issues	

Window Function	✓
Center Console	✓
Dash	✓
Sun Visors	✓
Dash Lights	✓
Dash Gauges	✓
Rear Defroster	✓
Carpet	✓
Floor Mats	✓
Cigarette Use	✓
Unusual Odors	✓
Cup Holders	✓
Headliner	✓
Blower Motor	✓
Interior Trim	✓
Inner Trunk	✓

Passenger's Front - No Issues
Driver's Rear - No Issues
Passenger's Rear - No Issues
Wheel Condition
Driver's Front - No Issues
Passenger's Front - No Issues
Driver's Rear - No Issues
Passenger's Rear - No Issues
Tire Tread
Driver's Front - 8/32
Passenger's Front - 8/32
Driver's Rear - 8/32
Passenger's Rear - 8/32



10/32 OR MORE

Tires have plenty of tread!
(standard)

8/32 OR MORE

Tires have plenty of tread!
(low profile)

5/32 TO 7/32

Tires will need replacement soon!

4/32 OR LESS

Tires need replacement!



2



3





5





7


































23











































































Note for Image 1:
side

Note for Image 2:
front

Note for Image 3:
rear

Note for Image 4:
side rear

Note for Image 5:
side rear

Note for Image 6:
windshield

Note for Image 7:
side front

Note for Image 8:
side front

Note for Image 9:
side front

Note for Image 10:
hood

Note for Image 11:
hood

Note for Image 12:
engine bay

Note for Image 13:
engine bay

Note for Image 14:
engine bay

Note for Image 15:
engine bay

Note for Image 16:
engine bay

Note for Image 17:
engine bay

Note for Image 18:
engine bay

Note for Image 19:
engine bay

Note for Image 20:
engine bay

Note for Image 21:
engine bay

Note for Image 22:
VIN

Note for Image 23:
interior

Note for Image 24:
interior

Note for Image 25:
interior

Note for Image 26:
interior

Note for Image 27:
interior

Note for Image 28:
interior

Note for Image 29:
rear seat

Note for Image 30:
trunk

Note for Image 31:
trunk

Note for Image 32:
trunk

Note for Image 33:

trunk

Note for Image 34:

driver side

Note for Image 35:

passenger side

Note for Image 36:

passenger side

Note for Image 37:

exterior

Note for Image 38:

wheel

Note for Image 39:

wheel

Note for Image 40:

exterior

Note for Image 41:

wheel

Note for Image 42:

wheel

Note for Image 43:

exterior

Note for Image 44:

exterior

Note for Image 46:

tealights

Note for Image 47:

tealights

Note for Image 48:

rear window

Note for Image 49:

rear

Note for Image 50:

grove box

Note for Image 51:

center console

Note for Image 52:

center console

Note for Image 53:

center console

Note for Image 54:

center console

Note for Image 55:

center console

Note for Image 56:

gouge cluster

Note for Image 57:

gouge cluster

Note for Image 58:

gouge cluster

Note for Image 59:

gouge cluster