

Date of Inspection: 1/21/2021


[Download Full-size Pictures \(zip\)](#)
Vehicle Inspection Report

Vehicle Information


Year	1954
Make	Plymouth
Model	Plymouth
Body	
Odometer	99482

CarDr.com Summary

Exterior is mostly fine, aside from potential issues on the . Interior is mostly fine, aside from potential issues on the . Mechanical is satisfactory. Undercarriage is satisfactory. Driving Test is satisfactory.



Reliability Score



Vehicle History Check Summary

CarDr.com is partnered with CARFAX for all vehicle history operations.






Key:  Satisfactory

 Attention Needed





 Unable to read

 Critical

On Board Diagnostic (OBD) Analysis

Check Engine Light Check	
Engine Misfire Monitoring	
Fuel System Monitoring	
Powertrain Electronics Monitoring	
Emissions Monitoring	

Vehicle Fraud Check

Distance Since Code Cleared	
VIN Fraud Check Windshield	
VIN Fraud Check OBD	
VIN Fraud Check Door Panel	

*Unable to read does not mean that an issue exists. It means that the vehicle did not support a standard OBD-II PID, its at manufacturers discretion.

Exterior & Interior

Exterior


1 Passenger Side Front

Door Glass



Cracked

2 Rear Window/Trim



Chrome Peel

3 Driver Side Front



Fender

4 Driver Side Front Door



5 Driver Side Front Door



Glass

6 Driver Side Front Door



Vent Windows

7 Driver Side Door Mirror



8 Driver Side Rocker



Panel

9 Driver Side Side



Moldings

10 Driver Side Rear Door



Glass

11 Driver Side Rear



Quarter

12 Driver Side Rear Turn



Signal

13 Driver Side Tail Lights



14 Trunk Pan



15 Rear Bumper



16 Passenger Side Tail



Lights

17 Passenger Side Rear



Turn Signal

Interior

1 Radio/Navigation



Under seat

2 Driver Side Front Door



Panel

3 Driver Side Front Door



Controls

4 Steering Wheel



5 Driver Side Sun Visor



6 Driver Side Front Seat



7 Driver Side Front Seat



Controls

8 Driver Side Front Seat



Belt

9 Driver Side Front



Carpet

10 Driver Side Floor Pan



Weak Spots

11 Dash Gauges



12 Dashboard



13 Audio Sound Level



14 Driver Side Rear Seat



15 Driver Side Rear



Carpet

16 Passenger Side Rear



Door Panel

17 Trim Strips



18 Passenger Side Rear



Seat

18 Passenger Side Rear Quarter	✓
19 Passenger Side Side Moldings	✓
20 Passenger Side Rocker Panel	✓
21 Passenger Side Door Mirror	✓
22 Passenger Side Front Door	✓
23 Passenger Side Front Door Vent Windows	✓
24 Passenger Side Front Fender	✓
25 Passenger Side Front Turn Signal	✓
26 Passenger Side Headlight	✓
27 Passenger Side Fog Light	✓
28 Grill	✓
29 Front Bumper	✓
30 Hood	✓
31 Driver Side Fog Light	✓
32 Driver Side Front Turn Signal	✓
33 Driver Side Headlight	✓
34 Windshield	✓
35 Wiper Blades	✓
36 Roof	✓
37 Convertible Top	✓

19 Passenger Side Rear Carpet	✓
20 Passenger Side Front Door Panel	✓
21 Passenger Side Front Door Controls	✓
22 Passenger Side Front Seat	✓
23 Passenger Side Front Seat Belt	✓
24 Passenger Side Front Carpet	✓
25 Passenger Side Floor Pan Weak Spots	✓
26 Floor Mats	✓
27 Passenger Side Sun Visor	✓
28 Cigarette Use	✓
29 Interior Odor	✓
30 Headliner	✓
31 Accessories	✓

<div>38</div> Convertible Top	<div>✓</div>
Hardware	
<div>39</div> Body Seals	<div>✓</div>
<div>40</div> Body Alignment	<div>✓</div>
<div>41</div> Exterior Paint	<div>✓</div>
Condition	
<div>42</div> Frame/Unibody	<div>✓</div>
Condition	
<div>43</div> Rust	<div>✓</div>

Mechanical	
Air Filter	✓
Battery Condition	✓
Charging System	✓
Cooling Fan Condition	✓
Radiator Cap Sealing	✓
Hoses	✓
Radiator	✓
Engine Coolant	✓
Water Pump	✓
Belts	✓
Power Steering	✓
Steering Fluid	✓
Engine Oil	✓
Inner Fender	✓
Firewall	✓
Shock Towers	✓
Carburetor	✓
Engine Covers	✓
Engine	✓
Transmission Fluid	✓
Brake System	✓

Road Test	
Engine Starting	<div>✓</div>
Engine Performance	<div>✓</div>
Transmission Performance	<div>✓</div>
Clutch	<div>✓</div>
Differential Performance	<div>✓</div>
Wheel Bearing	<div>✓</div>
Performance	
Braking Performance	<div>✓</div>
Parking Brake	<div>✓</div>
Suspension Performance	<div>✓</div>
Steering Performance	<div>✓</div>
Tire Pressure System (TPMS)	<div>✓</div>
Tire/Wheel	
Spare Tire	<div>!</div> <div>Missing</div>
Tire Manufacturer	<div>✓</div> <div>Pirelli</div>
Tread Depth	<div>!</div> <div>12/32</div>
Tire Size	<div>✓</div> <div>215/60/17</div>
Driver Side Front Tire	<div>✓</div>
Driver Side Front Wheel	<div>✓</div>

Brake Fluid	✓
Differential	✓
Exhaust System	✓
CV Joints and Axles	✓
Suspension	✓
Ball Joints and Tie Rods	✓
Key Fob/Key	✓
Undercarridge	✓
Idle Test	
Satisfactory	✓

Driver Side Rear Tire	✓
Driver Side Rear Wheel	✓
Passenger Side Rear Tire	✓
Passenger Side Rear Wheel	✓
Passenger Side Front Tire	✓
Passenger Side Front Wheel	✓

Additional Inspector Notes

Vehicle is in good condition overall.

Disclaimer

The Inspection is a parking lot inspection of a Mechanical Vehicle. The Vehicle may have been staged to hide problems and unobserved by the Inspector. The services from CarDr.com Inc are provided on an "as is" basis without warranties of any kind, either expressed or implied, including without limitation, warranties of title, non-infringement, or implied warranties of merchantability or fitness for a particular purpose.

Nothing in these terms or in any description of products or services in the services shall constitute a representation or warranty with respect to such products or services. you acknowledge, by your use of the services, that such use is at your sole risk. You agree that CarDr.com Inc's liability is limited to refunding the price you pay for the CarDr.com's inspection in the event you are dissatisfied with CarDr.com's service, or injuries occur due to an unreported defect in the vehicle. In no event shall either cardr.com or its affiliates or agents be liable for any direct, indirect, punitive, incidental, special or consequential damages arising out of or in any way connected with the use of the services, whether based on contract, tort, strict liability or otherwise, even if advised of the possibility of any such damages. By Ordering the service you agreed to the same. In the event this vehicle is from another country, warranties may not apply.











